



FIG. 1








FIG. 3





FIG. 4



P1 = 0*	000 * (P1a)
P2 = 1*	001*(P1b)
P3 = 11*	010*(P1c)
P4 = 101*	011*(P1d)
P5 = 10001*	100*(P2)
P6 = 1100*	101*(P4)
P7 = 110000*	110*(P3a)
P8 = 1100000*	111*(P3b)
	10001*(P5)
FIG. 6A	11000*(P6a)
	11001*(P6b)
	1100000 * (P8)
	1100001*(P7)

FIG. 6B




FIG. 7





FIG. 8







FIG. 10A






FIG. 10C






FIG. 10D










FIG. 13








FIG. 15




FIG. 16




FIG. 17




FIG. 18